10/650594

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

JUL 2 6 2005 entee:

Andre Schouten et al.

Docket:

50019.256US01

atent No.:

6,900,669 B1

Issued:

May 31, 2005

Title:

AREA EFFICIENT ON-CHIP TIMEOUT GENERATOR WITH LOW TEMPERATURE AND

LOW SUPPLY VOLTAGE DEPENDENCY

**CERTIFICATE UNDER 37 CFR 1.8:** 

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, with sufficient postage, in an envelope addressed to: Certificate of Correction Branch, Commissioner for Patents P.O. Box

1450 Alexandria, Virginia 22313-1450 July 22, 2005.

Name: Leslie A. Moss

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450

Sir:

We are transmitting herewith the attached:

Notice of Errors in Printed Patent

Return postcard

Please consider this a PETITION FOR EXTENSION OF TIME for a sufficient number of months to enter these papers, if appropriate. Please charge any additional fees or credit overpayment to Deposit Account No. 13-2725. A duplicate of this sheet is enclosed.

Merchant & Gould P.C. P.O. Box 2903 Minneapolis, MN 55402-0903 612.332.5300

Name: Mark R. Hennings

Reg. No.: 48,982

MRH:lam

23552

PATENT TRADEMARK OFFICE

Certificate

AUG 1 7 2005 of Correction





Patent No.:

6,900,669 B1

Docket:

50019.256US01

Issue Date:

May 31, 2005

Patentee:

Andre Schouten et al.

Title:

AREA EFFICIENT ON-CHIP TIMEOUT GENERATOR WITH LOW

TEMPERATURE AND LOW SUPPLY VOLTAGE DEPENDENCY

**CERTIFICATE UNDER 37 CFR 1.8:** 

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, with sufficient postage, in an envelope addressed to: Certificate of Correction Branch, Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450 July 22, 2005.

Name: Leslie A. Moss

## NOTICE OF ERRORS IN PRINTED PATENT

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450

Sir:

The following errors were noted in the above-identified issued patent:

Column 2, line 15, "arc" should be --are--.

Column 3, line 1, "to" should be  $--t_0$ --.

A Certificate of Correction is not believed warranted in this case, but the errors are hereby

made of record for the benefit of anyone reading the file of the issued patent.

Merchant & Gould P.C. P.O. Box 2903 Minneapolis, MN 55402-0903 612.332.5300

By: Mark R. Hennings

Reg. No.: 48,982

MRH:lam

23552

PATENT TRADEMARK OFFICE